

mechanism. Although it is unlikely, the defective part could break and cause the rifle to fire accidentally.

Remington Arms has launched a program to identify and recover all rifles made and sold during this period, and as a precaution, will replace the trigger assembly on every affected rifle without charge to the owner.

All Remington trade customers and individual rifle owners are being notified, and it is expected that this program will quickly identify owners of the affected rifles.

This notice applies only to those bolt action models listed. No other Remington firearms are involved.

If you have purchased one of these rifles since July 29, 1987, do not load it.

We ask that you call our Trigger Assembly Replacement Program at 1-800-634-2459 with the model and serial number of your rifle. From that number, we can tell you immediately if yours is one of the affected rifles, and if it is, how you can arrange for a free replacement of the trigger assembly.

Source:

- **Guns & Ammo, June 1988; page 89**
- **Rifle, July-August 1988; Volume 22, Number 4, page ?**
- **California Department of Justice Firearms Safety Note 88-3**