

year). Also make sure that your firing pin assembly has been taken apart and cleaned thoroughly. If it is gummed up and dirty this will interfere with the ignition of the firearm. Maintenance is the key for successful operation.

There are 3 types of ignition systems for the Model 700 ML:

Musket Cap (top hat)

#11 Percussion Cap

209 Shotgun primer (introduced in 2002) we offer a conversion kit for Models manufactured prior to 2002 for around \$40.00 from our retailers (we do not offer this as parts) We do not supply these for free for guns manufactured prior to 2002. This is the most effective ignition on the market.

We haven't made a side lock muzzle loader in more than 100 years EXCEPT for in 1995. This was designed in the custom shop and an anniversary edition. It was called the Eliphalet Anniversary Special. It had a 35" barrel with flint lock (the hammer hits a piece of flint for ignition).

We started the manufacture of Model 700 ML in 1996.

We do not make black powder or substitute. There are only 3 manufacturers of powder in the US: DuPont, the US Government and one other company. Laws governing the manufacture of black powder are very strict.

We test our Model 700 ML with Pyrodex granular powder. We recommend the use of granular powder over pellets for an accuracy standpoint.

Do not use smokeless powder in a Model 700 ML!!

Use a 7/16 in. deep socket wrench to take the musket cap nipple off and put a new one on.