

M/700 Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: NEW R #: 013812
 OUTSIDE WORK: SCOPE MOUNTED DATE: 7-12-72
 FROM: CHRISTMAN'S INC.
 FIRED AMMO TYPE: REMINGTON DARIEN, CT.
 & CONDITION: _____ GUN #: 6394467
 PROOF: R.E.P. ASSEMBLER 97 INSPECTION: 7A TEST: _____ CODE: XT = 12/70
 HEADING: O.K. GRA./CAL.: 222
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: 10 ROUNDS - O.K. APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR - SEAR ENGAGEMENT .010 (MIN.) .020 TRIGGER
PULL = 2 LBS. (MIN. 15 LBS.) NECK MEASURES .460 (MIN. .4518)
THROAT IS SHALLOW.

COMPLAINT: "CHAMBER NECK IS TOO SHORT, CHECK TRIGGER AT LIGHT SETTING"

INCIDENT: POTENTIAL FOLLOW DOWN.

COMMENTS: THIS RIFLE WAS RETURNED QUESTIONING THE FRONT
OF THE CARTRIDGE CASE BEING MARKED, WHICH IS
THE MARK OF THE CASE WIDING ACROSS THE RECHAMBER
IN BEING EJECTED. THE LIGHT TRIGGER PULL AND UNDER
MIN. ENGAGEMENT COULD HAVE LED TO A MORE SERIOUS
COMPLAINT LATER.

PLAINTIFF'S
EXHIBIT

3224

AL 0029756