

Bolt Action Centerfire – Bolt Lock Update Modification Program

Website text

- If your Model 600 or 660 rifle was repaired as part of the 1979 recall, or it was not subject to the 1979 recall, you may have the bolt-lock removed at a total cost of \$20, plus shipping and handling. By participating in this program you will also receive a transferable coupon good for up to \$20 towards the purchase of any Remington safety product, including gun locks, hearing and eye protection and gun safes.

If it was never serviced as part of the recall in 1979, we will install a new trigger that does not have the Bolt-Lock feature installed. The service will be free to you. See service directions below.

How to participate in the Safety Modification Program:

1. Complete the General Repair Form ([link to form](#)), and
2. Send or deliver your firearm and the completed repair form to either;
 - a. A Remington Authorized Repair Center ([link](#)); or
 - b. Ship your firearm to the Remington factory at:

Remington Arms Company, Inc.
Ilion Firearms Plant
Attention: BL Safety Program
14 Hoefler Avenue
Ilion, NY 13357

Remington will bill or arrange for payment once your firearm is received and evaluated.

CAUTION: It is your responsibility to comply with all laws and regulations regarding transportation or shipping of your firearm. Absolutely no ammunition should be packaged with the firearm either in the firearm itself or in its shipping container. The firearm should be transported only in a completely unloaded condition.

6/5/2006

2