

I saw a show 60 min or 48 hours. Along that line. And they were talking about...

Discussion Thread

Response (Laura) 2/13/2001 5:21:24 PM

At 02/13/2001 02:16 PM we wrote -

Dear Mr. Whiteman,

Thank you for your inquiry. According to the serial number provided, your firearm was produced approximately 1974 and has the bolt lock safety.

Remington considers all Remington firearms, including the Model 700 safe to us so long as you adhere to the "10 Commandments of Firearms Safety", keep it properly maintained and do not make inappropriate alterations. You can find the complete response that we forwarded to CBS regarding their broadcast on the front page of our website.

If you have any concerns regarding the safe functioning of your firearm we would be more than happy to help you get the firearm a safety check-up by a Remington Authorized Repair Center or our factory gunsmiths.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/Support/repairsvc/ModelSelection.asp>

Customer (Steven Whiteman) 2/11/2001 4:32:03 PM

I saw a show 60 min or 48 hours. Along that line. And they were talking about the Model 700 having a faulty SAFETY. I would like to know if My MODEL 700 has that safety. If it does I would hope that I could send it back to remington to have the problem fixed. I have always sworn by Remington products. And I hope that if I have one of these faulty safety's that Remington will correct the problem before something happens. Which I believe you will. So if you could let me know as soon as possible. I would appreciate it. I might of sent this letter with the wrong serial # Before the correct Serial # is 6727406.

Thank You
Steven M Whiteman
193 Conway St
Greenfield Mass 01301