

difficult to get into the chamber. The third and fourth rounds out of the magazine fed in quite smoothly. Is this normal? Could this be caused by a new magazine follower spring exerting a little too much upwards pressure on those first 2 rounds and just needing to be "broken in" a bit? I've not yet registered this rifle, and if it needs to be inspected, or worked on, I'd really hate to have to take it back to that dealer. In addition to the long drive, he's an older fellow with a small shop, and I doubt I'd get any help from him. If the rifle does need to be inspected or worked on, is there an authorized service center in, or near Kansas City that could do the work instead of shipping it back to the factory?

Thanks,
Adam Jacob
adamjacob@mac.com