

problem. Does every Model 700 have this potential problem, or is it a limited one? Should he contact the company or would a local gunshop be able to check his rifle? He still uses this rifle and plans to use it in Colorado in October for elk. Am looking forward to the answers. Jim