

3 Rifles to check please re bolt safety mods: Mdl 600 serial 6695972 Mdl 600 ...

Discussion Thread

Response (Derek)

4/29/2002 8:18:17 AM

Dear Phil,

Thank you for your inquiry. If the model 600's do not have the V stamped on the shooter's left-hand side of the trigger, they need to be returned to our factory in Ilion, NY. The model 700 shows to have been produced, in or around 1989, this firearm should not have the bolt lock feature.

Customer (Phil Smiley)

4/24/2002 9:25:48 AM

3 Rifles to check please re bolt safety mods:

Mdl 600 serial 6695972

Mdl 600 serial 6431075

Mdl 700 c6372677

Thank you

Phil Smiley