

Can you tell me exactly when my model 700 was manufactured? Here are some
fea...

Discussion Thread

Response (Laura)

10/16/2002 3:15:19 PM

Dear Brian,

Thank you for your inquiry. According to the information provided, this
firearm was manufactured in or around 1962. These firearms do not accept
stripper clips. You can send the stock to our factory for refinishing.
We also want to make you aware of a safety modification program that we
are offering on these and other Model 700 rifles. You can view this
information regarding this through the front page of our website or
through the link
below: http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Customer (Brian Calvert)

10/13/2002 11:54:06 AM

Can you tell me exactly when my model 700 was manufactured? Here are some
features: the receiver is drilled and tapped on the left and at the rear
for receiver sights, the receiver is also notched in front of the rear
scope mount holes for what I assume is stripper clip loading, the barrel
is 20 inches long, the barrel is marked "Remington Arms Co. Inc., Ilion,
N.Y. Made in U.S.A. Pat. No. 2,473,373 2,514,981 30-06 SPRG, at the rear
of the barrel on the left side just in front of the recoil lug it is
marked P J 46. I need to know: 1) When exactly was this rifle
manufactured? e.g. March 1973 2) Is the notch/slot on the receiver for
stripper clip loading? 3) Can Remington refinish this stock? Thank you so
much for your time in helping me solve these mysteries!