

this rifle is 30-06 caliber. based on the serial #, will you tell me when/where...

Discussion Thread

Response (Chris)

1/31/2003 10:54:30 AM

Dear Bob,

Thank you for contacting Remington Country. Your Model 700 was produced around 1975. Unfortunately, a description was not listed with the individual serial numbers on models manufactured before the mid-80's.

We would suggest sending it to a Remington Authorized Repair Center for inspection before using the firearm. They will check the trigger pull and can also remove the bolt-lock feature that your firearm may have. For more information on the bolt-lock and how to find a Remington Repair Center, go to:

http://www.remington.com/safety_modification_program/remington_safety.htm

Customer (bob diseker)

1/28/2003 11:12:37 PM

this rifle is 30-06 caliber. based on the serial #, will you tell me when/where it was manufactured, and any additional info specific to the rifle, if any? it currently has an old weaver 4x scope. it has a beautiful wooden stock, a ramp rear sight, but no front sight. the trigger has apparently been worked on - the weight is about 2 pounds. i have not taken it apart yet, but plan to install a bell and carlson medalist stock and burris signature scope. any suggestions on things to be alert for? semper fi bob