Model 700 30-06 #232189

Discussion Thread

Response (Chris) Dear Mr. Wilson, 10/1/2003 11:36:37 AM

Thank you for contacting Remington Country. According to the serial number you provided, your rifle was produced around 1966.

Your rifle was originally installed with a bolt-lock which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

we recommend taking/shipping the firearm to one of the following Remington Premier Repair Centers for inspection.

Bolsa Gunsmithing 7404 Bolsa Ave. Westminster, CA 92683 Phone: 714-894-9100 Fax: 714-898-9164

Allison & Carey Gun Works, Inc. 17311 SE Stark Portland, OR 97233 Phone: 503-256-5166

Sportsman's Haven, Inc. 14695 East Pike Rd. Cambridge, OH 43725 Phone: 740-432-7243 Fax: 740-432-3204

Mann & Son Sporting Goods 515 W Water St. Pinckneyville, IL 62274 Phone: 618-357-2911 Fax: 618-357-3658

Ahlman's, Inc. 9525 W. 230th Street Morristown, MN 55052 Phone: 507-685-4244 Fax: 507-685-4280 http://www.ahlmans.com/

Sports World, Inc. 5800 S. Lewis Ave. Suite 154 Tulsa, OK 74108 Phone: 918-742-4027 Fax: 918-72-3981

Paducah Shooters Supply, Inc. 3919 Cairo St. Paducah, KY 42001 Phone: 270-442-3242 Fax: 270-442-5022

Subject to Protective Order - Williams v. Remington