

Feedback for Answer ID 266 (Rated Helpfulness: 50%)

Discussion Thread

Response (Chris)

Dear Mr. Peterson,

Thank you for contacting Remington Country. If the Model 600 was produced before 1975 and does not have a "V" stamped on the trigger, we suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

To view more information on this safety message, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Customer (Mark Peterson)

This feedback is about:

http://remington.custhelp.com/cgi-bin/remington.cfg/php/enduser/std_adp.php?p_faqid=266.

add watreowl choke tubes to your answer