

I want to know about a recent recall on the safety mechanism. Cliff McGrath P...

Discussion Thread

Response (Chris)
Dear Mr. McGrath,

7/15/2003 9:14:43 AM

Thank you for contacting Remington Country. Only those Model 700 or 40-X rifles made before March 1982 were manufactured with a bolt-lock mechanism. Model 700 or 40-X rifles made after March 1982 do not have a bolt-lock mechanism and may be loaded and unloaded with the safety in the "S" or "On Safe" position. Consequently, post-1982 Model 700 or 40-X rifles are not subject to this bolt-lock Safety Modification Program.

For more information on the bolt-lock modification program, go to:

http://www.remington.com/Safety_Modification_Program/700_safety.htm

Customer (Clifford McGrath)

7/14/2003 6:23:26 PM

I want to know about a recent recall on the safety mechanism. Cliff McGrath
Please respond by e-mail above or phone
808-553-5963. Thanks.