

PROBLEMS WITH UNINTENTIONAL DISCHARGE WHEN CLOSING THE BOLT ...

Discussion Thread

Response (Chris)

7/17/2003 4:53:02 PM

Dear Mr. Bailey,

Thank you for contacting Remington Country. Your Model 600 was produced in 1965 and should be inspected for a trigger recall. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

To view more information on this safety message, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Customer (DAVID BAILEY)

7/16/2003 7:11:08 PM

PROBLEMS WITH UNINTENTIONAL DISCHARGE WHEN CLOSING THE BOLT.