

auto fire

Discussion Thread

Response (Chris)

3/31/2004 2:59:30 PM

Dear Mr. Brown,

Thank you for contacting Remington Country. Your Model 700 was produced in 1976. Your firearm has not been involved in a recall. Your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe.

To view more details regarding this modification, go to:

[http://www.remington.com/safety\\_modification\\_program/remington\\_safety.htm](http://www.remington.com/safety_modification_program/remington_safety.htm)

We recommend discontinuing use until the rifle can be inspected by a Remington Authorized Repair Center for the discharge problem. You can locate you closest center at:

<http://www.remington.com/repairsvc/modelselection.asp>

Customer (JOHN BROWN)

3/30/2004 9:26:47 PM

I STILL NEED HELP