

Rifle Safety

Discussion Thread

Response (Chris)

8/27/2004 12:21:10 PM

Dear Mr. Bruner,

Thank you for your patience. Your Model 700 was produced in 1971. Your firearm has not been involved in a recall. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

Your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Customer (Buddy Bruner)

8/23/2004 7:45:35 AM

I recently purchased two Remington Model 700 rifles from my uncle who had purchased them new several years ago. One of the rifles developed a problem and on two occasions while we were deer hunting it discharged without any apparent reason, even though the safety was on. I took the gun to a local gunsmith and he told me that there had been a recall on the rifle because of a problem with the trigger mechanism. He installed a new trigger mechanism and I am wanting to make sure that the gun is now safe. The rifle is a 22-250 caliber and the serial number is 6413344. Can you please check on this for me and also let me know if there is any known problems with the other rifle I also bought. It is a 25-06 caliber, and the serial number is 6440375. Both of the rifles are in excellent shape and are extremely accurate. I just want to make sure that there are no more problems that I need to address. Thanks for your help in this matter.