

Remington 600 Mohawk

Discussion Thread

Response (Chris)

3/2/2005 3:54:23 PM

Dear Bill,

By the serial number, your Mohawk 600 was produced around 1971 and should be inspected for a trigger recall. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

You can ship it yourself without an FFL and they will ship it back directly to you.

To view more information on this safety message, go to:

[http://www.remington.com/Safety\\_Modification\\_Program/remington\\_safety.htm](http://www.remington.com/Safety_Modification_Program/remington_safety.htm)

Customer (Bill Redding)

2/25/2005 9:26:01 PM

Chris, the Remington 600 Mohawk serial # 6392927. This rifle has the gold plated trigger. If I need to send the rifle somewhere to be modified, I don't have a FFL in my possession. Can I take the rifle to a gunsmith to have any modifications done if it has to be done? Thanks for your help, Bill