

MOHAWK 600 222

Discussion Thread

Response (Chris)

3/1/2005 8:30:11 AM

Dear Pat,

By the serial number you included, your Mohawk 600 was produced in 1977. The recall involved those produced before 1975.

Your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

[http://www.remington.com/safety\\_modification\\_program/remington\\_safety.htm](http://www.remington.com/safety_modification_program/remington_safety.htm)

Customer (PAT ARRINGTON)

2/28/2005 7:42:52 PM

I JUST BOUGHT A MOHAWK SER # A6460642 HAS IT BEEN SENT IN FOR THE SAFETY RECALL