

Three Remington rifle questions 30-06,7mm,7mm08

Discussion Thread

Response (Chris)

10/20/2005 11:03:53 AM

Dear Mr. Gray,

Thank you for your patience. The serial number starting with "C" was produced around 1990 and the "A" was produced around 1980.

Your firearms have not been involved in a recall. Your rifle that was produced in 1980 was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

You can find your nearest Remington Authorized Repair Center at:

<http://www.remington.com/repairsvc/modelselection.asp>

Remington recommends that the firearm be checked periodically by the Remington Arms Co or a Remington Authorized Repair Center. This will ensure proper inspection and any necessary replacement of worn or damaged parts.

Customer (GARY GRAY)

10/14/2005 9:02:16 PM

JUST CHECKING TO MAKE SURE I HAVE NOT BEEN OVER LOOKED. WOULD LIKE TO GET AN ANSWER AS SOON AS POSSIBLE ON THE SAFETY/TRIGGER ISSUE. NO HURRY ON THE 7400 QUESTION. THANKS!