

Bad Trigger Model 7 in 7mm-08.

Discussion Thread

Response (Dell)

11/1/2005 7:29:32 AM

Dear Edward,

Thank you for your inquiry. Based on the information you have provided, we suggest that you send your firearm to our Ilion, NY facility.

For U.S. repairs, please follow these guidelines:

1. Record the serial number of your firearm before sending it to us.
2. Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box, not a hardcase.
3. Remove all accessories from your firearm to prevent loss or damage. This would include scope, slings, or extra choke tubes.
4. Enclose a letter with the firearm detailing the model name or number of your firearm and serial number along with a full description of the problem. Be sure to include your full name and address (P.O. Box and Street Address), including zip code, daytime telephone number, and e-mail address.
5. Ship your firearm by either United Parcel Service (UPS) or Parcel Post (US Post Office). Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier. Customer is responsible for shipping charges to the factory.

For U.S. repairs only, ship to:

Remington Arms Company, Inc.  
Attn: Arms Services Division/Repairs  
14 Hoeftler Avenue  
Ilion, NY 13357

WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

If you have any questions as to the warranty on Remington firearms, please refer to our <a href="http://www.remington.com/support/warranty.htm" target="\_blank">Firearms Warranty </a>.

Customer (Edward Patton)

10/29/2005 2:14:27 PM

I am a gunsmith in Abbeville, South Carolina. A gentleman brought in a Model 7 where the trigger would not hold and the sear was dropping when the bolt was closed. No matter of trigger adjustment would work. It appears someone had gotten into the trigger before trying to fix it. Nothing will keep the sear from dropping when the bolt closes no matter how far the sear screw is turned in. He needs a replacement. What do you recommend? Send me a replace trigger or return the rifle to Remington.  
Thanks  
Ed Patton  
Cell 864-378-4916.