

7) Is this like the Safety Modification Program for Model 700's with bolt lock mechanisms?

No, this Safety Detent Spring Replacement program is unique to a limited number of Model 710's. The Model 710 was not a part of the Safety Modification program for Model 700's with bolt lock mechanisms.

8) Can I wait until after the season?

No! If your firearm was assembled with an improperly manufactured Safety Detent Spring, the spring must be replaced immediately.

9) Will my firearm be unsafe if I do not have this done?

Even if the improperly manufactured "Safety Detent Spring" causes the safety mechanism to malfunction, that by itself would not cause the rifle to fire. However, although it is unlikely, if your rifle was assembled with an improperly manufactured "Safety Detent Spring," then the spring may interfere with the ability of the manual safety to fully engage in the "safe" or "on" position. Moreover, the user may not be aware of the fact that the mechanism has not properly engaged. While the trigger must still be pulled to fire the rifle, this recall and spring replacement program is intended to insure that the manual safety of your rifles functions properly.

10) Why is this part restricted?

Because the spring is an integral part of the internal working mechanisms of the firearm, and part of the trigger assembly, we only provide the part to a limited number of our factory trained authorized gunsmiths. Remington has the same policy with regard to all its firearms, not just the Model 710.

11) Why are you replacing the safety spring?

Remington wants its customers to enjoy the shooting sports safely. Even if the improperly manufactured "Safety Detent Spring" causes the safety mechanism to malfunction, that by itself would not cause the rifle to fire. However, although it is unlikely, if your rifle was assembled with an improperly manufactured "Safety Detent Spring," then the spring may interfere with the ability of the manual safety to fully engage in the "safe" or "on" position. Moreover the user may not be aware of the fact that the mechanism has not properly engaged. While the trigger must still be pulled to fire the rifle, this recall and spring replacement program is intended to insure that the manual safety of your rifles functions properly.

12) How do I know if my rifle is involved?

By providing the serial # of your firearm we can identify whether your rifle may have been assembled with improperly manufactured Safety Detent Spring.

13) Do I have to pay for the modification?

No!

14) Where do I send my firearm?

2. Paducah Shooter Supply B. Remington Authorized Repair center in your area.