

**Sample Letter**

October 29, 2002

TO OUR AUTHORIZED FUNCTIONAL WHOLESALERS AND DIRECT DEALERS:

A/s Norma Projektilfabrik  
Attn: Mr. Frode Larsen  
P.O. Box 373 Okern  
0513 Oslo  
Norway

Dear Mr. Larsen,

Remington Arms Company has uncovered a problem that may develop with a small number of Model 710 series rifles and is requesting you hold further shipment of these guns that remain in your inventory until appropriate action has been taken. This letter provides you with the necessary details regarding our request.

The Model 710 series firearms involved were shipped August, September and October of 2002. A complete serial number listing of the involved rifles shipped to your business is enclosed.

Please note that Model 710 series rifles with serial numbers other than those shown on the attached list are not involved, and you need not take any action on those guns. Also, no other Remington gun models are involved.

During routine test firing, Remington discovered the possibility that an improperly manufactured "Safety Detent Spring" may have been assembled in a number of Model 710 series rifles. Although unlikely, the improperly produced part could possibly bind and give the shooter a false indication of the safety arm position on the trigger assembly.