

Subject to Protective Order - Williams v. Remington

KY	710	999999		FIRING PIN.	FIRING PIN.	21072	\$18.00	1	150713
KY	710	71028513	08-01	LOOKED OVER.	FUNCTION TESTED & CHECKED OVER.	21072	\$14.00	1	124035
KY	710	71030400	09-01	COCKED BOLT.	FUNCTION TESTED OK.	21072	\$14.00	3	150560
KY	710	71032367	12-00	FIRING PIN BROKE.	INSTALLED NEW BOLT BODY WITH N.S.	21072	\$18.00	7	150493
KY	710	71031386	08-01	BOLT WORKS HARD.	KNOCKED BURR OFF BOLT HEAD.	21072	\$14.00	1	124039
KY	710	71039809	11-01	BOLT WORKS HARD.	KNOCKED BURR OFF BOLT HEAD.	21072	\$14.00	1	124040
KY	710	71012344	04-01	BOLT STIFF.	NEW BOLT BODY.	21072	\$14.00	4	150550
KY	710	71022158	06-01	FEEDING PROBLEMS.	CUSTOMER TALKED WITH TODD P.	21072	\$14.00	11	150469
KY	710	71024579	07-01	M5	POLISHED CHAMBER AND UPDATED.	21072	\$24.00	1	150730
KY	710	71037574	11-01	BOLT BECAME UNCOCKED.	RECOCKED BOLT AND TESTED.	21072	\$14.00	1	124029
KY	710	71025307	07-01	WAY.	REINSTALLED RIGHT BACKER AND TESTED.	21072	\$14.00	1	150718
KY	710	71011662	04-01	BOLT STICKING.	REMOVED BURR FROM BOLT HEAD AND TESTED.	21072	\$14.00	7	150498
KY	710	71033844	10-01	BACK.	REMOVED BURR FROM BOLT HEAD.	21072	\$14.00	7	150527
KY	710	71030931	09-01	SCOPE.	REPLACED BOLT STOP AND SCOPE.	21072	\$14.00	11	150723
KY	710	71009754	03-01	ASSY PIN.	REPLACED BOLT ASSY PIN.	21072	\$14.00	4	150752
KY	710	71027691	08-01	STAY IN BOLT.	REPLACED BOLT BODY AND TESTED.	21072	\$14.00	7	150528
KY	710	71002416	12-00	BOLT BODY.	REPLACED BOLT BODY.	21072	\$14.00	7	150642
KY	710	71007402	02-01	LOCKED IN BOLT.	REPLACED BOLT BODY.	21072	\$14.00	8	124013
KY	710	71014308	04-01	LOCKED IN FIRING POSITION.	REPLACED BOLT BODY.	21072	\$16.25	7	124022
KY	710	71011188	04-01	M5	REPLACED BOLT BODY.	21072	\$14.00	1	150652
KY	710	71020889	06-01	WOULD NOT HOLD FIRING PIN IN.	REPLACED BOLT BODY.	21072	\$14.00	1	150535
KY	710	71003398	01-01	M5	REPLACED BOLT HANDLE.	21072	\$14.00	1	150575
KY	710	71007915	03-01	M5	REPLACED BOLT HANDLE.	21072	\$14.00	7	124019
KY	710	71008533	03-01	M5	REPLACED BOLT HANDLE.	21072	\$14.00	4	150753
KY	710	71002843	03-01	M5	REPLACED BOLT HANDLE.	21072	\$14.00	1	150726
KY	710	71015570	05-01	M5	REPLACED BOLT HANDLE.	21072	\$14.00	5	150746
KY	710	71010326	03-01		REPLACED BOLT HEAD.	21072	\$14.00	7	150505
KY	710	71023027	07-01	BOLT HEAD HAD BURRS ON IT.	REPLACED BOLT HEAD.	21072	\$14.00	7	150492
KY	710	71025924	08-01	CLOSE.	REPLACED BOLT HEAD.	21072	\$14.00	3	150559
KY	710	71031134	09-01	BOLT HEAD MISSING FROM BOLT.	REPLACED BOLT HEAD.	21072	\$18.00	7	150515
KY	710	71001540	12-00	UPDATE.	REPLACED BOLT SHROUD AND UPDATED.	21072	\$14.00	7	124016
KY	710	71033969	10-01		REPLACED BOLT STOP & ADJUSTED BOLT STOP CLIP.	21072	\$14.00	7	150514
KY	710	71005948	01-01	BOLT STOP.	REPLACED BOLT STOP.	21072	\$14.00	4	150454
KY	710	71005119	01-01	BOLT STOP.	REPLACED BOLT STOP.	21072	\$14.00	3	150732
KY	710	71004842	01-01	BAD BOLT STOP.	REPLACED BOLT STOP.	21072	\$14.00	11	150574