

REPLACED NEW GUARD ASSY.	20954	\$78.23	88	153560
DISASSEMBLED AND INSPECTED, GLASS BED FRONT				
OF ACTION AREA SO THAT ACTION DOESN'T SHIFT	20017	\$48.40	2	149767
DISASSEMBLED AND INSPECTED; ADJUSTED EJECTOR				
TO ENGAGE SHELLS DEEPER, ADJUSTED RETURN	20017	\$30.50	0	149770
DISASSEMBLED AND INSPECTED; ADJUSTED EJECTOR				
TO ENGAGE SHELLS DEEPER, TEST FIRED OK.	20017	\$43.12	4	149771
DISASSEMBLED AND INSPECTED, DOESN'T SHOOT				
ACCURATE GROUP, ADJUST SCOPE AND SITE IN GUN.	20017	\$29.00	0	149769
DISASSEMBLED AND INSPECTED, REPAIRED EJECTOR				
TO ENGAGE SHELL DEEPER, ADJUSTED BOLT RETURN	20017	\$45.12	0	149772
DISASSEMBLED AND INSPECTED; TIGHTENED CRAMMER				
ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER.	20017	\$48.52	2	149768
SENT TO FACTORY.	20124	\$15.40	2	161251
SENT TO FACTORY.	20124	\$14.51	1	74577
RESTRAPPED SPRING, TEST FIRED 15 ROUNDS.	20201	\$44.12	2	152947
WHSE INSPECTION.	107773	\$15.00	1	DK1307
WHSE INSPECTION.	107773	\$15.00	1	DK1306
WHSE INSPECTION.	107773	\$15.00	1	DK1305
WHSE INSPECTION.	107773	\$15.00	1	DK1383
WAREHOUSE INSPECTION.	107773	\$15.00	1	DK1429
WAREHOUSE INSPECTION.	107773	\$15.00	1	D1463
WAREHOUSE INSPECTION.	107773	\$15.00	1	DK1475
WAREHOUSE INSPECTION.	107773	\$15.00	1	DK1481
WAREHOUSE INSPECTION.	107773	\$15.00	1	DK1503
WAREHOUSE INSPECTION.	107773	\$15.00	1	DK1418
WAREHOUSE CHECK.	107773	\$15.00	1	6/10/02
WAREHOUSE CHECK.	107773	\$15.00	1	0
WAREHOUSE CHECK.	107773	\$15.00	1	6/10/02
WAREHOUSE CHECK.	107773	\$15.00	1	6/10/02
WAREHOUSE CHECK.	107773	\$15.00	1	6/10/02
WAREHOUSE CHECK.	107773	\$15.00	1	6/10/02
ADJUSTED FEEDING AND TEST FIRED.	20113	\$30.25	3	135846
REPLACED BOLT HANDLE RETAINING SPRING INSIDE				
OF BOLT.	20113	\$25.50	8	135895
REPLACED MAGAZINE.	20113	\$25.03	3	135861
REPLACED MAG ASSY, CHECKED EXTRACTOR AND				
TEST FIRED.	21102	\$40.78	25	123018
REPLACED BOLT HANDLE SPRING & RIVET.	21102	\$38.20	1	123013
DRILLED OUT BOLT HANDLE RET SPRING & RIVET AND				
INSTALLED NEW ONE.	21102	\$38.20	5	124490
REPLACED TRIGGER ASSY.	21102	\$60.23	70	124483