

RD-542-1 Rev. 2-15-61

P.I. NO GUN EXAMINATION REPORT NUMBER: _____

GENERAL CONDITION: NEW

OUTSIDE WORK: NO

FIRE AMMO TYPE: +

& CONDITION: +

PROOF: R.E.P.-C INSP.: 9 TEST: 49

HEADING: O.K.

BREACH OPENING: -

RECOIL SHOULDERS: O.K.

CHAMBER: O.K.

TEST: 40 ROUNDS REMINGTON

COMPONENT CONDITION: (Damaged, Broken, Old Style)

MODEL: 700 BDL VAR.

R # : 12943

DATE: 6-29-71

FROM: H.P. Cox

MEER HIGH SCHOOL
ARLEY, ALABAMA

GUN # : 6408250

CODE: LU 2/71

GR./CAL.: 223

CHECKED BY: C. PROSSER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

SEAR AND TRIGGER CONNECTOR CORNER BROKEN OFF,
ENGAGEMENT P.015 (.005 UNDER MIN.) FIRING PIN P.
RADIUS TOO LARGE.

COMPLAINT: FIRE ON CLOSING, FIRE WHEN SAFE WAS PUSHD
OFF, PIERCED PRIMERS.

INCIDENT: FOLLOWED DOWN.

COMMENTS: THE PRIMER PIERCING WAS NOT DUPLICATED IN TEST.
ING. IT MAY HAVE SPEEDED UP THE CONNECTOR - SEAR
BREAK-DOWN

PLAINTIFF'S
EXHIBIT

3271

1 of 1

AL 0029803