

ST	MODEL	SERIAL #	MFG YR	COMPLAINT	REPAIR	GUNSHOP	TOTAL	DAYS SHIP	INVOICE #
KY	710	71002443	12-00	UPDATE.	UPDATED.	21072	\$14.00	1	150659
KY	710	71002425	12-00	M5	UPDATED.	21072	\$19.00	3	150618
KY	710	71002462	12-00	MAG LATCH.	UPDATED.	21072	\$14.00	4	150635
KY	710	71002928	12-00	UPDATE.	UPDATED.	21072	\$14.00	4	150693
AL	710	71002183	12-00	SENT TO FACTORY.	SENT TO FACTORY.	21056	\$8.50	1	138574
SD	710	71002885	12-00	SENT TO PADUCAH.	SENT TO PADUCAH.	20510	\$26.97	1	137555
SD	710	71002413	12-00	SENT TO PADUCAH.	SENT TO PADUCAH.	20510	\$25.13	1	137620
MI	710	71002587	12-00	FAULTY BOLT.	REMOVED BURR ON STRIKER	20108	\$30.00	6	142168
NE	710	71002572	12-00	BOLT HANDLE BROKEN OFF. PLASTIC BOLT SHROUD BROKEN.	SENT TO FACTORY. REPLACED BOLT SHROUD AND	21138	\$32.92	1	37699
KY	710	71001540	12-00	UPDATE.	UPDATED.	21072	\$14.00	7	124016
KY	710	71001902	12-00	M5	UPDATED.	21072	\$14.00	4	150542
KY	710	71002710	12-00	M5	UPDATED.	21072	\$14.00	8	124011
KY	710	71002670	12-00	BOLT STOP BROKEN, TRIGGER GUARD BROKEN.	REPLACED STOCK & BOLT STOP AND UPDATED.	21072	\$17.50	1	124038
KY	710	71001951	12-00	MAG LATCH BROKEN.	REPLACED MAG LATCH.	21072	\$14.00	5	150750
KY	710	71002416	12-00	FIRING PIN ASSY WON'T STAY IN BOLT BODY.	REPLACED BOLT BODY. INSTALLED NEW BOLT BODY	21072	\$14.00	7	150642
KY	710	71002367	12-00	FIRING PIN BROKE.	WITH N.S. REPLACED FIRING PIN	21072	\$18.00	7	150493
KY	710	71002413	12-00		MECHANISM.	21072	\$14.00	7	150530
KY	710	71002740	12-00	M5	UPDATED.	21072	\$14.00	7	150526

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010174

MAE00010090