

KY	710	71006483	02-01	TRIGGER GUARD & TRIGGER BROKEN.	REPLACED TRIGGER AND GUARD.	21072	\$14.00	7 150489
KY	710	71007518	02-01	BOLT SAFETY DOES NOT WORK. BOLT WILL NOT GO DOWN INTO CHAMBER.	REPLACED FIRING PIN ASSY. RETURNED TO FACTORY FOR REPAIR, RETURNED TO	21072	\$18.00	1 150580
OH	710	71007402	02-01	BOLT HEAD & FIRING PIN STUCK IN CHAMBER.	SENT GUN TO FACTORY.	21060	\$44.50	16 SH4799
CA	710	71006554	02-01	BAD SCOPE.	ALIGNED SCOPE.	20106	\$30.29	1 149395
CA	710	71006608	02-01	WAREHOUSE INSPECTION.	WAREHOUSE INSPECTION.	107773	\$15.00	1 DK1265
MS	710	71006991	02-01	M5		21072	\$14.00	1 157584
KY	710	71007292	02-01	BROKEN TRIGGER GUARD.	REPLACED STOCK AND SPRING.	21072	\$17.50	5 124097
KY	710	71006664	02-01	CHAMBER RUSTY. BOLT HANDLE BROKE, SCOPE FOGGY.	CLEANED AND TEST FIRED.	21072	\$14.75	1 157654
KY	710	71006822	02-01	STOCK CRACKED AROUND BOLT STOP AREA, BOLT STOP BROKEN.		21072	\$14.00	1 157662
KY	710	71006946	02-01	M5	REPLACED BOLT BODY.	21072	\$17.50	6 157584
KY	710	71006405	02-01	FIRING PIN ASSY BROKEN.		21072	\$14.00	3 157572
KY	710	71007158	02-01	BOLT STOP BROKEN.		21072	\$14.00	1 157577
KY	710	71010378	03-01	M5	UPDATED.	21072	\$14.00	4 150625
KY	710	71008688	03-01	SCOPE BAD.	REPLACED SCOPE.	21072	\$14.00	1 150663
KY	710	71008052	03-01	WILL NOT GROUP, BOLTS HARD.	UPDATED AND TESTED.	21072	\$25.25	1 150669
KY	710	71008828	03-01	SCOPE.	REPLACED SCOPE.	21072	\$14.00	4 150668
KY	710	71007847	03-01	UPDATE.	NEW BOLT BODY.	21072	\$14.00	4 150628

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010181

MAE00010097