

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: GOOD R #: 044 04
 OUTSIDE WORK: NO DATE: 3-1-71
 FIRED AMMO TYPE: — FROM: GLOBE #10
 & CONDITION: _____ TUCSON, ARIZONA
 GUN #: 6319824
 PROOF: R.E.P.-E INSP.: 58 TEST: NO STAMP CODE: AT-3/70
 HEADING: O.K. GA./CAL.: 270 WIN.
 BREECH OPENING: — CHECKED BY: C. R. Rauer
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO COMPONENT DAMAGED OR BROKEN. TRIGGER-CONNECTOR
SEAR ENGAGEMENT 0.005 (MIN. IS 0.015)

COMPLAINT: FIRES ON CLOSING BOLT

INCIDENT: FOLLOW DOWN

COMMENTS: THE TRIGGER CONNECTOR-SEAR ENGAGEMENT IS
NOT ENOUGH FOR PROPER SUPPORT, ALLOWS THE
FIRING PIN TO FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3280

AL 0029812

1 of 1