

1. Fuzzy optics on some scopes
2. Crosshairs rotated approx. 30 deg. on 1 scope
- \* \* Box bottoms - Falling off during shooting
- \* \* Magazine followers - Sticking in box (cause of stem low malfunction)
- \* Safety in Fire Position as received - 1 of 30
- \* "Pillar bedding" on hang tag
- \* Box removal difficult - varies
- \* Bolt Stops Loose - detent force varies
- \* Trigger position relative to trigger guard - side to side
- \* Take down screws - loosening during shooting
- \* Scope rail deformation

The topics in red are classified as potential show stoppers. These effect function and short term customer perception. We will discuss all topics in more detail at 4:00 today.