

criteria. The gun in question is going to have both the receiver insert and bolt dimensions measured to determine if they exceeded specification. Again, the issue at hand is how to appropriately measure the forces required to cycle the bolt. As with the camming force, I feel a quantitative test is needed here in order to set acceptance criteria.

All in all, I felt that the evaluation went well. Although there are areas in which we can improve, the guns were suited to move forward with the test.

Any questions, please let me know.

John C. Trull
Product Manager - Firearms
Remington Arms Company, Inc.
Phone: (336) 548-8737
Fax: (336) 548-7737
trulljc@remington.com
www.remington.com