

P.I. ND GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: Good R #: 03978
 OUTSIDE WORK: NO DATE: 3-1-71
 FROM: ERBACHERS SPORTS CENTER
 FIRED AMMO TYPE: - MARLBOROUGH, OHIO
 & CONDITION: _____ GUN #: 278328
 PROOF: R.E.P. INSP.: D TEST: 87 CODE: CP-4/37
 HEADING: O.K. GA./CAL.: 7MM MAG.
 BREECH OPENING: - CHECKED BY: C.P.
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO COMPONENT DAMAGE OR BREAKAGE.

COMPLAINT: "FIRED TWOTIMES WHEN CLOSING BOLT."

INCIDENT: FOLLOW DOWN

PLAINTIFF'S
EXHIBIT

3281

COMMENTS: TRIGGER CONNECTOR-SEAR ENGAGEMENT .025. THE
TRIGGER ETC. WAS FOUND TO BE COATED WITH A HEAVY-
GREASE-LIKE LUBRICANT WHICH WOULD CAUSE TRIGGER
RETRACTION TO BE ERRATIC. THIS APPARENTLY HAPPENED
TO THE CUSTOMER - TRIGGER DID NOT RETRACT AND
WHEN THE BOLT WAS CLOSED THE FIRING PIN
FOLLOWED DOWN.

1 of 1