BARBER - REM DOCSB0012545

REPAIR AT N/C GOODWILL

REPAIR AT SPEC PRICE

REPAIR AT SPEC PRICE

REPAIR AT SPEC PRICE REPAIR AT SPEC PRICE PER SAFETY MOD. PROG. RIFLE NEVER UPDATED REPLACE TRIG ASSEM AT N/C

REPAIR AT SPEC PRICE

REPAIR AT SPEC PRICE

REPAIR AT N/C

REPAIR AT SPEC PRICE

REPLACE REC., BBL, AND TA

REPAIR AT SPEC PRICE

INSTALL NEW TAINS

QUOTE NEW TA \$20 BL PROGRAM

QUOTE NEW TA \$28 BL PROGRAM

CLEAN, INSTALL NEW TA-BL

PROGRAM

QUOTE \$20 FOR NEW TA BL PROGRAM

REPAIR AS NEEDED N/C

