

The trigger pull should never be anywhere near 10 lbs. It is too bad that we could not get this gun as we would be able to research who built the fire control, the gun and who inspected it with some analysis. I have no answers otherwise.

I will however review this with the guys to see that we are following proper procedures in all three areas.

Jon

-----Original Message-----

From: Trull, John

Sent: Monday, January 12, 2004 1:42 PM

To: Perniciaro, Stephen; Waldo, Jonathan W.; Shoemaker, Christopher D.

Subject: 700 BDL Trigger Pull

Guys,

Just got my hands on a real gem today. Linda Powell in our press department ordered a M700 BDL .30-06 (RAMAC 5793) Serial Number G6301069Z (the Z looks like it was stamped on the receiver after the rest of the serial number was rolled if that means anything). The gun has a trigger pull weight that is averaging 10lbs. Linda needs this gun next week for a hunt. I can lower the trigger pull weight myself, but I have to wonder how and why this got out like this. I would like to get your feedback this afternoon before I make any alterations to the gun at all.

Thanks,

John C. Trull

Marketing Manager - Firearms Division

Remington Arms Company, Inc.

P.O. Box 700

870 Remington Dr.

Madison, NC 27025-0700

(336) 548-8737 - Phone

(336) 548-7737 - Fax

john.trull@remington.com

www.remington.com