

Phillip Reesor

From: Chamblee, Danny
Sent: 03/12/2004 05:25:53 PM
To: Reesor, Phillip K.
CC: Byrd, Shane R.; Golemboski, Matt R.; Roudabush, Kathy; Underwood, Harold W.
BCC:
Subject: RE: 710 Receiver Insert Test

Phillip,

We need these guns back at your earliest convenience.

I believe that return procedure would be:

At E-Town

Enter a transfer to Mayfield SAP location with no SAP transaction

Give Customer service necessary to prepare a RGA for the total quantity of guns returned.

At Corporate

Process the RGA to Mayfield

At Mayfield

Receive the transfer in DMS (updates DMS inventory)

Process the RGA (updates SAP inventory)

This being the process, the 62 504 returned were not handled properly in SAP (DMS is fine) and we have overpaid excise taxes. To correct, we need an RGA for 62 504 to correct our SAP inventory.

If you have any questions or comments (or know a better way), please let me know.

Thanks,
Danny Chamblee
Accounting Manager
Remington Arms Company, Inc.
Mayfield Plant
22 Rifle Trail, PO Box 99
Hickory, Ky 42051
Tel: (270)856-4210
Fax: (270)856-3233
E-Mail: danny.chamblee@remington.com
Visit Remington on the Web at remington.com

-----Original Message-----

From: Reesor, Phillip K.
Sent: Friday, March 12, 2004 1:04 PM
To: Chamblee, Danny
Subject: RE: 710 Receiver Insert Test

Not sure what the test involves. I will do everything possible to have returnable and sellable guns at the end of the test. Also I have some gun right now that could be returned. I have 7- 30.06 rifles that were sent for the first safety detent test that was never done and I have 6- 30.06 & 6- 270 rifles that were not shot but were drop tested (one with a stripped receiver take-down screw hole).

Phillip

-----Original Message-----

From: Chamblee, Danny
Sent: Friday, March 12, 2004 1:24 PM

Subject to Protective Order - Williams v. Remington