

Todd.Golem@Remington.com

-----Original Message-----

From: Trull, John
Sent: Wednesday, October 22, 2003 9:22 AM
To: Golem, Todd E.; Shoemaker, Christopher D.
Cc: Joy, Robert L.; Perniciaro, Stephen
Subject: RE: Problem with Rifle for Sports Afield Test.

Todd,

I have one here. The gun is on my consignment account, so I will need it back, or it will need to go back on a RGA. I would prefer to send it to your attention and then get it back as I am afraid that if we RGA it, it will end up on the rack as a WIP gun. Does it need to come to your attention? Also, this gun had an issue with the bolt binding when the front take down screw was torqued to spec. The screw appears much too long, so you guys may want to have someone review this as well.

Thanks,

John Trull
Product & Planning Manager, Firearms
Remington Arms Co., Inc.
(336) 548-8737 Phone
(336) 548-7737 Fax
john.trull@remington.com
www.remington.com

-----Original Message-----

From: Golem, Todd E.
Sent: Wednesday, October 22, 2003 8:44 AM
To: Shoemaker, Christopher D.
Cc: Joy, Robert L.; Trull, John; Perniciaro, Stephen
Subject: RE: Problem with Rifle for Sports Afield Test.

Chris,

I will begin to look into the fire control issue, but it would be VERY helpful to have an example of one of these rifles with a hard force safety. Would it be possible to get one to me?

Regards,
Todd E Golem
Quality Engineer
Ext.-3364
Pager-157

-----Original Message-----

From: Shoemaker, Christopher D.
Sent: Tuesday, October 21, 2003 5:37 PM
To: Perniciaro, Stephen
Cc: Golem, Todd E.
Subject: FW: Problem with Rifle for Sports Afield Test.

Steve, I think the action on the take down screw torque and length is a process issue and belongs to your group. I will ask Todd Golem to add the fire control quality issue to his list of to do's when he is not tied down with 2100 tasks.

-----Original Message-----

From: Trull, John