

John Trull

From: Trull, John
Sent: 10/22/2003 11:20:46 AM
To: Golem, Todd E.; Shoemaker, Christopher D.
CC: Joy, Robert L.; Perniciaro, Stephen
BCC:
Subject: RE: Problem with Rifle for Sports Afield Test.

Todd,

Will do. The serial number is G6315765. If you guys don't mind, please change the fire control out with one that operates easier if possible before returning it.

Thanks,

John Trull
Product & Planning Manager, Firearms
Remington Arms Co., Inc.
(336) 548-8737 Phone
(336) 548-7737 Fax
john.trull@remington.com
www.remington.com

-----Original Message-----

From: Golem, Todd E.
Sent: Wednesday, October 22, 2003 11:06 AM
To: Trull, John; Shoemaker, Christopher D.
Cc: Joy, Robert L.; Perniciaro, Stephen
Subject: RE: Problem with Rifle for Sports Afield Test.

John,

Please send it to my attention and I will return it to you when I am done with it. I can dimensionally review both issues and let you know.

Kind Regards,
Todd E Golem
Quality Engineer
Remington Arms Company, Inc.
14 Hoefler Avenue
Ilion, New York 13357

(315) 895-3364
(315) 895-3670 Fax
Todd.Golem@Remington.com

-----Original Message-----

From: Trull, John
Sent: Wednesday, October 22, 2003 9:22 AM
To: Golem, Todd E.; Shoemaker, Christopher D.
Cc: Joy, Robert L.; Perniciaro, Stephen
Subject: RE: Problem with Rifle for Sports Afield Test.