

the trigger to return to full engagement. This presents the appearance of the trigger binding as the firing pin is being cocked.

This will be easily and readily resolved by reviewing the aforementioned tolerance stack ups so that this rifle will perform like the other two. This is then how ALL rifles will perform should we be awarded this contract.

Page 2

Deficiencies continued:

5) We will correct this by further sanding out the bolt handle channel on the stock. This should have been done after the bedding process and apparently was omitted.

All of these issues will become part of our assembly process and final inspection process to insure no FBI guns leave the factory should we win this solicitation. In fact, we are implementing several new assembly and quality control processes based on these guns getting out with out these items being checked.

Per our phone discussion, Norm Chandler, Jr. and I will be at the academy on Monday to resolve these issues.

I apologize for the problems and promise to take care of this in a most expedient manor. Thank you for the opportunity to make these corrections.

Sincerely,

Gregory A. Foster

Gregory A. Foster
Manager, Law Enforcement
And Government Sales