BARBER - REM DOCSB0016819

We still do the 3200 update, takes 8 – 12 weeks on repairs. 1977 needed to make adjustments to the 3200. Strengthens the receiver \$350 for the update. When in reality we use \$900 worth of parts and labor.

Factory only performs update on 3200. Laib's Gunsmithing has all parts and will repair

