

Remington Arms Company, Inc.
Summary
2002 Bolt-Action Safety Modification Program

Models Covered:

Certain Bolt Action Firearms made prior to March, 1982:

- Model 700
- Models 600 and 660 (including Mohawk 600)
- Model 721
- Model 722
- XP-100
- 40-X

Program Basics:

Cleaning, inspection and removal of bolt-lock feature from safety arm.

Allow customers to have certain older bolt-action firearms modified and updated to allow unloading and loading of the firearm while the manual safety is kept in the "S" or "On Safe" position. The customer no longer has to move the manual safety to the "F" or "off or Fire" position to load or unload the firearms.

Program is voluntary, that is, the customer has the decision whether to participate

Program Cost to Customers and Program Rebate:

1. Customer pays \$20.00 for clean, inspect and bolt-lock mechanism removal
2. Customer receives a coupon good for \$20.00 rebate on purchase of the following Remington Safety Products:
 - a. Hearing Protection
 - b. Eye Protection
 - c. Trigger block or cable lock
 - d. Gun Locker
 - e. Gun Safe

Where Consumers Can Get More Information:

1. Go to www.remington.com - look for Safety Modification Program message on home page in **Safety 1st Section**
2. Call Remington on toll-free number set aside for the Safety Modification program: (877) 387-6691