

| | | | |
|---------------------------|-------------|----------------|-----------|
| Model | 660 | | |
| Total Units | 50,536 | | |
| Last date of production | 1971 | | |
| Recalled | Yes | | |
| Date | 1979 | | |
| Estimated Units worked on | <10,000 | | |
| Cost of Repair | | | |
| | Non Updated | "V" Updated | |
| Parts | 12.03 | 0 | |
| Labor | 15 | 15 | |
| Overhead | 25 | 25 | |
| Total | 52.03 | 40 | |
| Estimated Returns % | 2.0% | 2.0% | |
| Estimated Returns - Units | 1,011 | 1,011 | |
| Fee | 0 | \$ 20 | |
| Cost | \$ 52.03 | \$ 20 | |
| Net Cost | \$ 52.588 | \$ 20,214 | \$ 72,802 |

Notes

1979 recall

Product already had a recall on guns made through February 1975

Installed new firecontrol with bolt lock on it.

Production starting in March of 1975 had new f/c with bolt lock

V on fire control means it has been updated

New Update Program - 2001**February 1975 and prior Production**

A If no "V" on F/C put a new model 700 F/C in it

B IF "V" on Fire control

- 1 Clean, lubricate & keep existing fire control and cut off tab - gun in good working condition
- 2 Firecontrol altered or state of disrepair - Get new fire control - Part # F91469
- 3 Have cleaned, keep bolt lock feature and get a video on safe gun handling