FAULT CATEGORY	OLD CODE NEW	N CODE	MALFUNCTIONS MO	DELS
FINISH	η	M118	POOR FINISH - FORE END	
FINISH	ŗ	M119	POOR FINISH - RECEIVER (OR FRAME)	
FINISH	P	M120	POOR FINISH - STOCK	
FINISH	M019 N	VI122	RUSTED COMPONENT	
FINISH		VI126	STOCK MARRED	
BROKEN PART		V1103	BUTT PLATE / RECOIL PAD IS BROKEN	
BROKEN PART		M125	STOCK CRACKED	
BROKEN PART		W1125	EXTRACTOR IS BROKEN	
BROKEN PART		V1145	BOLT HANDLE FELL OFF, BOLT IS BROKEN	
BROKEN PART		W153	RECEIVER PLUG SCREWS BROKEN	
DROKENPART	ľ	VIIOS	RECEIVER PLUG SCREWS BROKEN	
EALL T CATECORY	OLD CODE NEW	W CODE	MALEUNICTIONS MO	DELS
FAULT CATEGORY			MALFUNCTIONS MO ACCURACY	DELS
OUT OF SPECS			I SACANS " SACANS AND	
OUT OF SPECS		M104	CHAMBER ROUGH / RINGS / TEARS / TIGHT	
OUT OF SPECS		M109	DAMAGES CASES BULLETS OR SHELLS	
OUT OF SPECS		M112	HEADSPACE IS EXCESSIVE	
OUT OF SPECS		VI113	MUZZLE DAMAGE	
OUT OF SPECS	M032	M121	RECEIVER IS MISCUT	
OUT OF SPECS	M020	M124	SIGHTS OFF CENTER	
OUT OF SPECS	M028	M127	TRIGGER PULL IS OUT OF FACTORY SPECS.	
OUT OF SPECS	M058	VI128	CHAMBER DIRTY / RUSTY	
OUT OF SPECS		VI130	HEADSPACE AT MINIMUM	
OUT OF SPECS	ľ	M132	BLUING SALTS ARE BLEEDING FROM METAL	
OUT OF SPECS	M048 N	M133	EXTRACTOR MISSING	
OUT OF SPECS		VI135	TRIGGER CONNECTOR BINDS	
OUT OF SPECS		VI139	RIFLING ROUGH / MISCUT / DAMAGED	
OUT OF SPECS		V1144	ROLL MARKING VISIBLE INSIDE BORE	
OUT OF SPECS		VI154	RECEIVER SCOPE MOUNT HOLES OFF CENTER	
OUT OF SPECS		M155	BOLT FACE / SHROUD DAMAGED	
OUT OF SPECS		M156	BORE IS HEAT CHECKED	
OUT OF SPECS		M161	EJECTOR STUCK IN BOLT	
OUT OF SPECS		566	FREEBORE MISCUT / MIN	
OUT OF SPECS		VI103	SCOPE MOUNT THREADS UPSET IN RECEIVER	
			Mac 10000	
OUT OF SPECS		VI173	BARREL BRACKET OUT OF POSITION	
OUT OF SPECS		M174	BOLT STOP STICKS	
OUT OF SPECS		M177	STOCK NOT BEDDED PROPERLY	
OUT OF SPECS		V1178	TRIG ADJ SCREWS RESET, CANNOT READJUST	
MISCELLANEOUS	300	M102	BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER REPAI	JR
MISCELLANEOUS		105	CONSIGNED GUN	
MISCELLANEOUS	3553355	20000000	COULD NOT DUPLICATE CUSTOMERS COMPLAINT	
MISCELLANEOUS	M062	M107	CREDIT RETURN	
MISCELLANEOUS	200000000000000000000000000000000000000	W108	DAMAGE APPEARS TO HAVE OCCURRED IN TRANSIT	
MISCELLANEOUS	M050	V114	NO CORRESPONDENCE	
MISCELLANEOUS	M038	M115	NO FAULT FOUND AT BENCH	
MISCELLANEOUS	M045	M116	PACKING ERROR	
MISCELLANEOUS	M037	V123	SAFETY CONCERN, EXAMINED BY PRODUCT SERVICE	
MISCELLANEOUS	1.0	VI140	ACTION IS DIFFICULT TO OPEN	
MISCELLANEOUS		V175	ISS BOLT LOCKED IN THE "OPEN" POSITION	
FUNCTION	A STATE OF THE STA	W110	FAILS TO FIRE	
FUNCTION	***************************************	M129	FAILS TO EXTRACT	
FUNCTION	***********	W134	FAULTY MAGAZINE	
FUNCTION		VI137	FAILS TO EJECT	
FUNCTION	000000000000000000000000000000000000000	M138	WILL NOT FEED PROPERLY	
FUNCTION	2001 2000000000	M141	EXTRACTOR IS CATCHING ON SHELL HEAD	
FUNCTION	2000000	M142	MAGAZINE DIFFICULT TO LOAD	
FUNCTION	1. Victory	``	EJECTOR DOES NOT HAVE ENOUGH TENSION	
55540		M160		
FUNCTION		M172	CLOSES HARD OVER SHELL	
FINISH	7777777777777777	M111	FINISH IS DAMAGED ON TRIGGER GUARD/PLATE	
FINISH			POOR FINISH - BARREL	
- 1 - 1 - 4000 0000 0000 0000 0000 0000		M117		
FINISH FINISH)	VIII7 VI118 VI119	POOR FINISH - FORE END POOR FINISH - RECEIVER (OR FRAME)	