

Contents

1. Legal Standard of Fraud
2. “Legal Fees” – Remington Expenditures CNBC Response
3. Broadcast Response Transcript
4. Barber Quote – *Remington Under Fire* – Oct. 20, 2010
5. Remington Official Statement to CNBC
6. Remington “Fact” Statements
7. Remington Facts v. Barber Facts

Exhibits:

- A. General Denial- Customer Complaints
- B. Listed Malfunctions – Known Functional Deficiencies
- C. “The Debris Theory”
- D. Abuse & Neglect
- E. History of “Trigger Adjustments”
- F. History: The “Fails to Fire Malfunction”
- G. “The Trick Condition” – FSR Malfunction
- H. “The Screw-Driver Test” – FOS Malfunction – Slip Fit of Connector on Trigger
- I. Part I - 1948 Trigger Block Design
- I. Part II – Deficiency: Prior Sear Block Safety Design (Pre Model 700)
- I. Part III – Model 700 Recommended Design Improvements (Post Model 700)
- J. History: “10 Commandments of Safe Gun Handling”

Contents

K. Direct Impeachment of Remington Statement – Affidavits & Hull Order

L. “Salt Bleed-Out Corrosion – A Bi-Product of Powder Metal Construction

M. Factory Applied Lubricant –

Remington’s acknowledgement Steelguard causes safety related malfunctions in their products.