GUN #

PROOF TEST

A-1	HAD TO HAMMER BOLT BACK. (LOT # N220C6523)
A-2	HAD TO HAMMER BOLT BACK, SIGNS OF LEAKAGE, CASE
	STUCK IN BOLT AND EJECTOR STUCK BACK (LOT # N220C6523)
A-3	HAD TO HAMMER BOLT BACK. (LOT #N220C6523)
A-4	HAD TO HAMMER BOLT BACK, SIGNS OF LEAKAGE, CASE
	STUCK IN BOLT, EJECTOR STUCK BACK AND BOLT HANDLE
	BROKE OFF. (LOT # N220C6523)
A-5	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
A-6	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
A-7	HAD TO HAMMER BOLT BACK 🤃 OT # D15UB0623)
A-8	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
A-9	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
A-10	HAD TO HAMMER BOLT BACK. (LOT.#.D45UB0623)
A-11	HAD TO HAMMER BOLT BACK (LOT # D15UB0623)
A-12	HAD TO HAMMER BOLT BACK. (LQT # D15UB0623)
A-13	HAD TO HAMMER BOLT BACK. (LOT#D15UB0623)
A-14	OK

GUN

PROOFTEST

B-1	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-2	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-3	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
В-4	HAD TO HAMMER BOLT BACK, BROKE BOLT HANDLE OFF.
	(LOT # D15UB0623)
B-5	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-6	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-7	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-8	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-9	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-10	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-11	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-12	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-13	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-14	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)

REDO PROOF TEST ID PUT IN A-2 HAD TO HAMMER BOLT

A-2	TOOK BOLT FROM B-1 AND PUT IN A-
	BACK. (LOT#D15UB0623)
A-4	TOOK BOLT FROM B-2 AND PUT IN A-

TOOK BOLT FROM B-2 AND PUT IN A-4 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)

Subject to Protective Order - Williams v. Remington