***************************************	,900,000 m
Revise floor plan and schedule review	J.Doolittle
Obtain drill presses (One two spindle and a one spindle)	G Wilks
	J.Balio
Need set up for new crib location	***************************************
First Article on sear spring support 301441	Joe Diliberto
New tool for common side plates from Square Stamping	J.Doolittle
First Article on side plates 301435	Joe Diliberto

