

> Cc: James, Will; Boyles, Derek; Thompson, Jeff; Riley, Gary D.
> Subject: RE: 8/6/03 Mayfield meeting
>
> Here are the items for review.
>
> Print Discussions
> Safety Arm Blank - The arm angle is greater than print requirements, width is to
narrow on the arm, and the thumb pad is angled downward.
> Trigger Pull Spring - Free length and wire diameter
> Sear Return Spring - Wire diameter.
> Trigger Guard Screw - Outside head profile radius is too small.
> Bolt Cam Lock - .060 radius was to be changed to +/- .010 at .070
> Take Down Screw - Outside head profile radius is too small. O.D. of head too
small.
>
> Assembly Issues
> The receiver and bolt cam lock assembly, mag box changes, and the stock fit.
>
> A review of our assembly process is needed.
>
> Trigger Assembly
> Brian Rages is needed to set up trigger scan and a review of our process is
needed.
>
> Thanks,
>
> Ed Thweatt

> -----Original Message-----
> From: Stone, Jeff
> Sent: Tuesday, August 05, 2003 7:45 AM
> To: Thweatt, Ed T.
> Cc: Norton, Vince; James, Will
> Subject: 8/6/03 Mayfield meeting
> Importance: High
>
> Ed, so that Vince I can prepare for the meeting tomorrow, please
provide us a list of items that we need to address.
> Thanks,
> Jeff S