		_	
FSST	Front sight tipped	] 0 "	
RSTT	Rear sight tipped	0	
RSBR	Rear sight base raised	0,35,55	
FSTR	Front sight raised	<b>0</b>	
FSTL	Front sight loose	j o	
RSTL	Rear sight loose	0	
MGPT-G	Missing parts at target	. 0	2,446,644,644
UNCN-G	Uncoded nonconformity at target	0	
Al-P	Assembly incompleye at proof	0	S
BC-P	Blows cases at proof	1 o	2000. 1888 1884.
BEB-P	Barrel extension broken at proof	0	
BLP-P	Blanked primer at proof		5.50
BP-P	Blown primer at proof	1 o	
BS-P	Barrel split at proof	9	
DLOS-P	Doesn't lock over shells at proof	, a	
ESB-P	Ejector sticks back at proof	Ö	
FCB-P	Fore-end cracked at proof	0	
FESO-P	Fore-end shot off at proof	р Б	
		- 1000000000000000000000000000000000000	
FF-P	Falls to fire at proof		
GCSO-P	Gas cylinder shot off at proof	0	
GRSO-P	Guide ring shot off at proof		
MCSO-P	Magazine cap shot off at proof	<i>V</i>	
MSI-P	Magnaflux stamp illegible on bbl	0	
MSM-P	Magnaflux stamp missing on bbl	0	
PP-P	Pierced primer at proof	0	
SCB-P	Stock cracked or broken at proof	]0	
UNC <b>M</b> -P	Uncoded proof malfunctions	0	
anada garasa na angananana angana	200000		
	à	*	
á			
*			
	<b></b>		
Subject to Protective Order	www.arns v. Remington		
***************************************			