

Jerry Allen

---

From: Bullis, Gene R.  
Sent: 01/06/2006 07:42:40 AM  
To: Allen, Gerald R.  
CC:  
BCC:  
Subject: FW: Action Log - 700 FC issues

---

From: Orf, Robert J.  
Sent: Thursday, January 05, 2006 5:57 PM  
To: Perniciaro, Stephen; Kilborne, Carl C.; Kelly, John W.; Call, Virginia L.; Bullis, Gene R.; Truax, Sheldon F.; Mroz, John B.; Bullis, Gene R.; Call, Virginia L.  
Cc: Bennett, Gary; Paestella, Michael M.; Diliberto, Joseph  
Subject: RE: Action Log - 700 FC issues

I do not agree with having the final assemblers adjusting fire controls for trigger pull. We need to get the other items addressed and should be gathering all of the fire controls that are rejected by the builders and have them re-inspected by the fire control assembly department. If these fire controls are set to the specs and do not meet our criteria for creep etc. they should be turned over to engineering for inspection.

DO NOT HAVE FINAL ASSEMBLERS ADJUSTING FIRE CONTROLS!!!!

Thanks

Bob Orf

---

From: Perniciaro, Stephen  
Sent: Thu 1/5/2006 4:28 PM  
To: Orf, Robert J.; Kilborne, Carl C.  
Cc: Bennett, Gary  
Subject: FW: Action Log - 700 FC issues

FYI