		3338	
FOOT	Transcials tipped		
FSST RSTT	Front sight tipped	0 <sup>%</sup>	
RSBR	Rear sight tipped Rear sight base raised	0	
FSTR		11111	
FSTL	Front sight raised Front sight loose	a O	fatos.
RSTL		\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \	
MGPT-G	Rear sight loose Missing parts at target		
		9	
UNCN-G	Uncoded nonconformity at target	0	
Al-P	Assembly incompleye at proof	0	
BC-P	Blows cases at proof	0	
BEB-P	Barrel extension broken at proof	0	notifie
BLP-P	Blanked primer at proof	0	
BP-P	Blown primer at proof	0	
BS-P	Barrel split at proof	0	<b>\</b>
DLOS-P	Doesn't lock over shells at proof	0	i
ESB-P	Ejector sticks back at proof	0	
FCB-P	Fore-end cracked at proof	0	
FESO-P	Fore-end shot off at proof	D	
FF-P	Falls to fire at proof	<b></b>	
GCSO-P	Gas cylinder shot off at proof	0	
GRSO-P	Guide ring shot off at proof	D.	
MCSO-P	Magazine cap shot off at proof		
MSI-P	Magnaflux stamp illegible on bbl	0	
MSM-P	Magnaflux stamp missing on bbl	0	
PP-P	Pierced primer at proof	0	
SCB-P	Stock cracked or broken at pigg!	0	
UNCM-P	Uncoded proof malfunctions	0	
***************************************			
		¥	
Ti de la companya de			
	<b></b>		
Subject to Protective Order	Williams v. Reminaton		
1			