TLW 03001

TEU 0300 Au

m/710		E	Engagement			soar Lift			
		1	2	3	4	GAP	-	2	3
Sample	Ser. No.								
B-1	71001124	,0297	0298	6288	,0315	1003	,0122	,0139	, 0,33
B-2	71001184	.6 277	16278	10268	.0301	10037	.0127	,0132	, 0131
B <b>-3</b>	71001244	,0282	10291	10272	£833	10049	1015	,0145	,0147
B-4	71001288	1032	.0311	.0307	.0345	0	10151	10173	10167
B-5	71001421	,0268	,027	,0a6	.0291	8000	10134	.0123 %	
B-6	71001462	,0262	. 0261	.0259	,0297	,0025	1012	10124	.0121
B-7	71001504	, 6294	,0299	10294	.0328	10038	,0154	.0139	70136
B-8	71001511	ou+	0++6	5+					
B-9	71001524	.0265	.0267	10281	.6297	10007	10138	.0132	16145
B-10	71001529	,0287	.0283	,0302	10302	٥	.0123	,0141	,0141
B-11	71001534	.0311	1031	.0306	, 033	,0026	10141	10137	,0131
B-12	71001535	,0273	,0283	,0286	,0309	,0023	.0144	.0137	,013
B-13	71001539	10291	,0295	.0299	,0329	10017	10152	.0143	.0146
B-14	71001559	10314	10308	10315	10352	.0032	1013	0106	.0149
B-15	71001578	1029	10279	:0293	1032	.0026	10162	. 3مان	01883
B-16	71001580	10307	,6304	,6313	.0334	,0043	-0156	المانات.	so i 5/8-÷
B-17	71001583	,0360	0375	.0366	,0412	0,	0137		0137
B-18	71001584		.0272	.0286	10282	10026	1014	40138	10138
B-19	71001595	.0286	.0282	.0286	10312	002/	10119	0119	1011
B-20	71001605	10262	,0271	1026	03/8	0024	10/75	10153	,0165
B-21	71001613	10256	10256	6251	,029	0	,0151	,0146	,0145
B-22	71001623		10273	10262	10297	1004	0134	,0/34.	101414
,B-23	71001632	.0267	.0271	0278		1001	,0126	1015	,0157
B-24	71001634	10279	276	.0288	∵ ω33 <sup>4</sup>	0	,0145	.0141	10/49
B-25	71001643	1,000	10304	10312	10308	10018	.0156	.013	10149
B-26	71001647		10285	10292	.0296	10014	:0129	.0/38	,0135
B-27	71001724		10304	,0299	10315	.0017	.0163	,0/13	.0175
B-28	71001760	10344	,036	.0367	.0381	0	.0171	.0127	.0149
B-20	71001782		,0293	.0303	,0302	0	10/62	10154	
9-30	71001789	10284	10285	10307	,0822	10019	10128	10/38	,0/3/

. Note: \* measured engagement at 20x magnification

Fig.

<sup>+</sup> B-5 missing near takedown screw

<sup>+</sup> stock screws are not torqued