HOT FUNCTION-TEST

PROJECT # 241095

TRACKING # TLW 0300AG

- # 1 PLACE GUN C 21 AND 100 ROUNDS AMMO IN PRE-HEATED CHAMBER FOR 13 HOURS AT 120 DEGREE F.
- # 2 TOOK GUN C 21 AND 20 ROUNDS OF AMMO OUT OF PRE-HEATED CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND FOUR ROUNDS IN MAGAZINE.

CYCLED SAFETY EVERY FIVE ROUNDS.

PUT GUN C 21 BACK IN PRE-HEATED CHAMBER FOR 2 HOURS.

3 AFTER 2 HOURS TOOK GUN C 21 AND 20 ROUNDS AMMO OUT OF PRE-HEATED CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND FOUR ROUNDS IN MAGAZINE.

CYCLED SAFETY EVERY FIVE ROUNDS.

PUT GUN C 21 BACK IN PRE-HEATED CHAMBER FOR 2 HOURS.

4 AFTER 2 HOURS TOOK GUN C 21 AND 20 ROUNDS AMMO OUT OF PRE-HEATED CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND FOUR ROUNDS IN MAGAZINE.

CYCLED SAFETY EVERY FIVE ROUNDS.

PUT GUN C 21 BACK IN PRE-HEATED CHAMBER FOR 2 HOURS.

- # 5 AFTER 2 HOURS TOOK GUN C 21 AND 20 ROUNDS AMMO OUT OF PRE-HEATED CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.
 - LOADING ONE ROUND IN CHAMBER AND FOUR ROUNDS IN MAGAZINE CYCLED SAFETY EVERY FIVE ROUNDS.
- # 6 AFTER 2 HOURS TOOK GUN C 21 AND 20 ROUNDS AMMO OUT OF PREMEATED CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.
 - LOADING ONE ROUND IN CHAMBER AND FOUR ROUNDS IN MAGAZINE CYCLED SAFETY EVERY FIVE ROUNDS.
- # 7 CLEANED AND INSPECTED FIRING PIN HEAD (LOOSE) FIRING PIN TIP (LOOSE)

